Received: 03/30/2017 Status: CANCELLED Effective Date: 04/01/2017

PSC NO: 15 ELECTRICITY LEAF: 205.1

COMPANY: CENTRAL HUDSON GAS & ELECTRIC CORPORATION REVISION: 15
INITIAL EFFECTIVE DATE: 04/01/17 SUPERSEDING REVISION: 14

Issued in Compliance with Order in C.16-E-0616 dated March 10, 2017

SERVICE CLASSIFICATION NO. 5 (Cont'd)

AREA LIGHTING SERVICE (Cont'd)

MONTHLY RATE (Cont'd)

1.B <u>Lamp, Fixture and Pole Package</u> (Cont'd)

						Monthly Charge Effective		
	Lamp		Fixture	Lamp	Fixture	July 1,	July 1,	July 1,
	Watts	<u>Lamp Type</u>	Watts	Lumens	<u>Type</u>	<u>2015</u>	<u>2016</u>	2017
**	400	Metal Halide	464	36,000	Cutoff Rectangular	37.68	41.47	44.90
	70	Sodium	86	5,800	Colonial Post Top	16.32	17.96	19.45

^{**} The charges for these packages apply to existing installations only. These fixtures are no longer available for installation at new locations. Upon failure, fixtures will not be replaced in kind.

Monthly Charge Effective

1.C. <u>Decorative and Specialty Lighting</u>

	Lamp <u>Watts</u>	Lamp Type	Fixture <u>Watts</u>	Lamp <u>Lumens</u>	Fixture <u>Type</u>	July 1, 2015	July 1, 2016	July 1, <u>2017</u>
	70	Sodium	86	5,800	Acorn Decorative	\$12.61	\$13.88	\$15.03
	85	Induction	85	6,000	Acorn Decorative	16.59	18.26	19.77
	175	Metal Halide	205	14,000	Acorn Decorative	12.59	13.85	15.00
**	150	Sodium	180	16,000	Victorian Gaslight	13.05	14.36	15.55
	250	Sodium	316	27,000	Highway Setback	11.92	13.12	14.21
	400	Sodium	496	50,000	Highway Setback	11.17	12.29	13.31
	250	Metal Halide	300	20,500	Highway Setback	13.23	14.56	15.76
	400	Metal Halide	464	36,000	Highway Setback	14.93	16.43	17.79
**	250	Sodium	316	27,000	Decorative Teardrop	22.49	24.75	26.80
**	400	Sodium	496	50,000	Decorative Teardrop	25.13	27.65	29.94
**	250	Metal Halide	300	20,500	Decorative Teardrop	23.33	25.67	27.79
**	400	Metal Halide	464	36,000	Decorative Teardrop	25.19	27.72	30.01

^{**} The charges for these fixtures apply to existing installations only. These fixtures will no longer be available for installation at new locations. Upon failure, fixtures will not be replaced in kind.