Received: 11/30/2018 Status: CANCELLED Effective Date: 09/01/2019

PSC NO: 15 ELECTRICITY LEAF: COMPANY: CENTRAL HUDSON GAS & ELECTRIC CORPORATION REVISION:

INITIAL EFFECTIVE DATE: 04/01/19 SUPERSEDING REVISION: 17

205.1

Monthly Charge Effective

18

SERVICE CLASSIFICATION NO. 5 (Cont'd)

AREA LIGHTING SERVICE (Cont'd)

MONTHLY RATE (Cont'd)

1.B <u>Lamp, Fixture and Pole Package</u> - This package includes lamp, fixture, photocell, fiberglass pole and necessary mounting hardware.

		,				Monthly Charge Effective		
	<u>Lamp</u> <u>Watts</u>	Lamp Type	Fixture Watts	<u>Lamp</u> <u>Lumens</u>	Fixture Type	<u>Apr 1,</u> 2019	July 1, 2019	<u>July 1, 2020</u>
**	175	Metal Halide	205	14,000	Cutoff Rectangular	\$33.47	\$36.07	\$39.90
**	250	Metal Halide	300	20,500	Cutoff Rectangular	39.37	42.43	46.93
**	400	Metal Halide	464	36,000	Cutoff Rectangular	46.98	50.63	56.01
**	70	Sodium	86	5,800	Colonial Post Top	20.35	21.93	24.26

1.C. <u>Decorative and Specialty Lighting</u>

						Monuny	Monuny Charge Effective		
	<u>Lamp</u> <u>Watts</u>	Lamp Type	Fixture Watts	<u>Lamp</u> <u>Lumens</u>	<u>Fixture Type</u>	<u>Apr 1,</u> 2019	<u>July 1,</u> 2019	<u>July 1,</u> 2020	
**	70	Sodium	86	5,800	Acorn Decorative	\$15.73	\$16.95	\$18.75	
**	85	Induction	85	6,000	Acorn Decorative	20.69	22.30	24.67	
**	175	Metal Halide	205	14,000	Acorn Decorative	15.70	16.92	18.72	
**	150	Sodium	180	16,000	Victorian Gaslight	16.27	17.53	19.39	
**	250	Sodium	316	27,000	Highway Setback	14.87	16.03	17.73	
**	400	Sodium	496	50,000	Highway Setback	13.93	15.01	16.60	
**	250	Metal Halide	300	20,500	Highway Setback	16.49	17.77	19.66	
**	400	Metal Halide	464	36,000	Highway Setback	18.62	20.07	22.20	
**	250	Sodium	316	27,000	Decorative Teardrop	28.04	30.22	33.43	
**	400	Sodium	496	50,000	Decorative Teardrop	31.33	33.76	37.34	
**	250	Metal Halide	300	20,500	Decorative Teardrop	29.08	31.34	34.67	
**	400	Metal Halide	464	36,000	Decorative Teardrop	31.40	33.84	37.43	

^{**} The charges for these fixtures apply to existing installations only. These fixtures will no longer be available for installation at new locations. Upon failure, fixtures will not be replaced in kind.